

*Status Report of the Berkeley Paths Network
Berkeley Path Wanderers Association, June 2020*

Berkeley has about 140 public paths and stairways. These walkways were drawn on the original plat maps of the City, they exist on City property, and are all built except for 22. They are used for recreation and for pedestrian connections to public transit and they can be critical for evacuations in emergency situations. The Berkeley Path Wanderers Association (BPWA) has been working for 22 years to raise awareness of the paths and to eventually complete the path network by constructing one to two new paths per year. Attached to this report is a list of the 36 paths BPWA built to date (Attachment A) and the paths still to be built (Attachment B). Our volunteers also maintain the paths by sweeping, weeding, and cutting back encroaching vegetation. We are an all-volunteer group; our fiscal sponsor is Berkeley Partners for Parks.

Many of the paths were built contemporaneously with the surrounding homes and other structures as Berkeley grew (Rose Walk, the Bancroft Steps and Vine Lane would be examples). These historic paths are largely concrete and were engineered and constructed by the City or by developers.



*Trail work on the lower segment of Halkin Walk,
June 2020*

The BPWA-built paths are ‘landscaped’ paths using three-foot wood ties with rebar anchoring them to the soil. The work is done by trained volunteers and all materials are paid for by donations. We install handrails when possible, though this is expensive and often times cost-prohibitive for our non-profit. BPWA volunteers are currently working to build Lower Halkin Walk, from Cragmont Ave to Euclid Ave. Completion is expected later this year.

The enclosed is a report on what remediation is needed to bring the path network into good condition. The findings are largely based on a field survey that BPWA organized on July 22, 2018. On that day nearly 80 volunteers fanned out all over the city and, clipboards in hand, walked all the paths and recorded their condition (signage, steps, handrails, overgrowth, etc.). The report is a living document; it is periodically updated to reflect progress made since the time of the July 2018 field survey. Going forward, we plan to conduct all-paths surveys once every five years.

Since then, BPWA has prioritized repairs of wood tie steps and vegetation clearing of overgrown paths at our volunteer maintenance parties. Through these parties, we work on 12-15 paths each year. BPWA has also alerted the City of Berkeley Department of Public Works (DPW) on work that our volunteers cannot perform and where we need the City to step in – such as adding street signs or performing structural and handrail repairs on the historic concrete paths. DPW has been adding the missing signage (see Table 1), performed

structural repairs on historical concrete paths (see Table 2), and addressed handrails that needed repairs (see Table 3). Funds are very limited and this type of work, especially concrete repair work, is resource intensive, but we are hopeful that one or two historical paths could be addressed each year. We are excited about the recent progress made improving the path network and look forward to updating the community on future efforts. BPWA is extremely grateful to our committed volunteers and supporters without whom this work would not be possible.

Please email Alina Constantinescu, BPWA President, at info@berkeleypaths.org with questions or information needs regarding this report. For more information on BPWA, our website can be found at www.berkeleypaths.org.

Findings summarized in this report

- | | |
|--|--|
| Table 1. Paths with missing/ inaccurate signs | Attachment A: Paths developed by BPWA since 1998 |
| Table 2. Paths with major structural issues | Attachment B. List of undeveloped paths |
| Table 3. Paths with broken handrails | Attachment C. Complete handrail inventory |
| Table 4. Paths that need handrails | |
| Table 5. Paths in need of vegetation maintenance | |

Examples of issues summarized in the report



Uneven/ broken steps on concrete path



Broken step on landscaped path



Steep path, no handrails



Damaged signs

Table 1. Paths signs inventory.

Note 1: Table shows signs still missing/ inaccurate as of June 2020. There were 183 (!) missing signs at the time of the July 2018 survey, but the City has been working on adding missing signs since then. Progress has been outstanding

Note 2: City of Berkeley is responsible for all signage, except in Park Hills subdivision. The Park Hills paths are listed at the end of the table; they are not part of the missing sign counts in Note 1.

#	Path	Bottom Signs		Top Signs		Address for missing signs/ Other comments
		Path	Cross St	Path	Cross St	
1	Cedar Path	✓	✓	✓	✓	Top sign needs to be moved from the street to the top of the stairs. The path is hidden and a sign is needed to mark the public access point.
2	Keeler Path	✗	✓	✗	✗	Existing signs are wrong. This is Keeler Path, not John Muir Path.
3	La Vereda Steps	✓	✓	✓	✓	Need additional sign mid-way where it crosses La Vereda again.
4	Scott Newhall Path	✓	✓	✓	✓	South sign (between 80-90 Hill Rd) needs to be moved closer to the path start. The path is hidden and a sign is needed to mark the public access point. Could use sign half-way through (at chain link fence) to help with navigation.
The paths below are located in the Park Hills subdivision. They are private property, owned and maintained by the PH Homes Association.						
5	Crescent Park Path	✗	✗	✗	✗	Bottom: between 9-14 Wilson Circle Top: between 1504-1506 Summit Rd
6	Fred Herbert Path (Lower)	✗	✗	✗	✗	Bottom: Wildcat Canyon Rd Top: between 1113-1115 Hillview Rd
7	Fred Herbert Path (Middle)	✗	✗	✓	✗	Bottom: between 1112-1114 Hillview Rd Top: between 1125-1141 Woodside Rd
8	Fred Herbert Path (Upper)	✓	✗	✓	✓	Bottom: between 1130-1138 Woodside Rd
9	Patty Kates Path	✓	✗	✗	✓	Bottom: between 1088-1100 Woodside Rd Top: between 1077-1103 Park Hills Rd Note: Could use signs to locate the path across the grassy area
10	Wildcat Path	✗	✗	✗	✓	Bottom: Wildcat Canyon Rd Top: between 1149 Hillview Rd & 1169 Park Hills Rd

Table 2. Paths with major structural issues.

Note: Table shows only paths identified as having major structural issues in the July 2018 All-Paths Survey. Many other paths not listed here have other, less severe issues (small cracks, uneven pavement from roots, etc.). BPWA plans to re-assess all paths once every 5 years.

Path	Issues noted in July 2018 survey
High Priority: Historic paths with concrete steps - City makes repairs	
Ranked in order of severity, i.e., worst shape/most treacherous at the top of the list.	
1	Redwood Terrace very uneven, heaved concrete steps Update: path fixed June 2020
2	Sterling Path very uneven, broken and heaved concrete steps and landings Update: path fixed October 2019
3	Tunbridge Lane uneven pavement at bottom, upper steps heaved and very uneven
4	Visalia Steps uneven, heaved steps; cracked pavement
5	Bret Harte Way some concrete steps tilted; concrete slabs missing at two handrail sections Update: path fixed June 2020
6	Florida Walk lowest section of steps heaved/ broken
7	Garber Path deteriorating/ crumbling steps
8	Great Stoneface Path very poorly installed asphalt, uneven, unsafe
9	Holmes Path some heaved steps
10	La Vereda Steps severely damaged concrete at top of path; bottom steps slanted and one cracked
Landscaped paths with wooden steps - BPWA makes repairs during maintenance parties, 12-15 per year.	
1	Acacia Steps top flight ad-hoc, dangerous, all bit treacherous
2	Betty Olds Path ✓ rebar needs pounding through-out
3	Cedar Path ✓ rebar sticking up in a few places; loose step halfway up; steps are crooked. Path was evaluated post-survey - needs rebuild to conform to newer BPWA standards.
4	Covert Path (Lower) lower switchback: step is angled and out of alignment; retaining wall rotten; midway before bridge loose step; protruding rebar
5	Covert Path (Upper) loose/ rotten steps on top of new staircase
6	Fred Herbert Path (Upper)* some steps are loose; rebar sticking up
7	Halkin Walk (Upper) ✓ rebar (multi), gopher holes undermining steps (top), protruding boards (top)
8	Keeler Path ✓ protruding rebar, some holes in dirt, broken step edges, round wooden beam protruding near park section
9	Miller Path East ✓ rebar sticking up in multiple spots; cracked concrete at the top
10	Mosswood Lane ✓ tripping hazard at the top of the path between curb and path; rebar sticking up
11	Oak Street Path (West) multiple rotten and protruding rebar steps
12	Poppy Path ✓ many instances of protruding rebar; some raised steps (needs soil fill-in), broken step in middle; wobbly steps near the top
13	Stevenson Path (Lower) ✓ rebar sticking up throughout
14	Stevenson Path (Upper) ✓ several rotten steps; mole holes; rebars needs pounding; steps need better rise+run b/w gates, perhaps add middle steps; few wobbly steps at the top
15	Wildcat Path* rebar and loose steps an issue throughout. June 2020 update: PG&E planning to remove gas line in area of the path; BPWA plans to re-build and clean up the path soon after PG&E work is complete.

Path	Issues noted in July 2018 survey
16 Wilson Walk ✓	most steps can use rebar pounding, gopher holes an issue, one rotted-out step
✓ June 2020 update: BPWA has already improved these paths with volunteers' work.	
*Path located on Park Hills property	

Table 3. Paths with handrails in need of repairs, as identified in the July 2018 survey.

Note: City of Berkeley DPW were notified of issues and subsequent repairs were conducted. As of June 2020, all handrail repairs are complete. BPWA plans to re-assess all paths once every 5 years.

Path	Issues noted in July 2018 survey
✓ Acacia Walk	loose 3rd from bottom
✓ Billie Jean Walk	This handrail was not flagged during the July 2018 survey; but DPW conducted improvements in May 2019.
✓ Bret Harte Way	The handrail is loose and very low (difficult to use). Note: This handrail was not flagged during the July 2018 survey. BPWA was alerted to it, and in turn notified DPW, in September 2019. Handrail repairs were made at the time the path concrete work was done in June 2020.
✓ Hill Court Steps	wobbly
✓ Indian Rock Path (Arlington Ave to Indian Rock Ave)	loose/wobbly in street median on south side of path
✓ Mosswood Lane	wooden handrail broken
✓ North Path	loose/wobbly in places; 3rd down dangerous
✓ Pine Path	multiple sections of wobbly handrail
✓ Redwood Terrace	one handrail section is broken
✓ Rock Walk	2nd handrail from top loose, loose concrete blade at top handrail
✓ Upton Lane	loose/wobbly throughout
✓ Vine Lane	loose in middle section
✓ City of Berkeley DPW were notified of issues and subsequent repairs were conducted since the time of the July 2018 survey.	
✓ BPWA volunteers conducted repairs Fall 2018.	

Table 4. Paths that need more handrail coverage to ensure safer usage.

Note: For a complete handrail coverage inventory, please see Attachment B.

Path	Existing handrail coverage and needs as of July 2018	Length	
Historic paths with concrete steps (City makes improvements)			
1	Arden Path	Partial coverage; handrail needed for steps on bottom section	tbd
2	Boynnton Walk	No handrails; handrail needed for the sections with stairs	tbd
3	Devon Lane (Lower)	No handrails; needed throughout except near picnic table at bottom	tbd
4	Easter Way (Lower)	Partial coverage; handrail needed for top section	tbd
5	El Paseo (Lower)	Partial coverage; handrail needed for top section with steps	tbd
6	Garber Path	Partial coverage; handrail needed on sections with stairs	tbd
7	Holmes Path	No handrails; handrail needed on sections with stairs	tbd
8	Oak Knoll Path	No handrails; handrail needed in middle section	tbd
9	Oakridge Path East	No handrails; handrail needed throughout, section with stairs at Domingo end is a priority. Neighbors contacted Lori Droste and Public Works	tbd
10	Oakridge Path West	No handrails; needs handrail on stairs in lower section of path	tbd
11	Orchard Lane (Upper)	Partial coverage; handrail needed on steps above #101	tbd
12	Park Path	Partial coverage; handrail needed on sections with stairs	tbd
13	Tunbridge Lane	Partial coverage; handrail needed on top section with stairs	tbd
14	Visalia Steps	No handrails; handrail needed on all sections with stairs	tbd
15	Yosemite Steps (Upper)	Partial coverage; handrail needed on top section with stairs	tbd
Landscaped paths with wooden steps (both City and BPWA could make improvements)			
1	Atlas Path	No handrails; could use full handrail, esp. on mid and top sections.	tbd
2	Bret Harte Path	Partial; handrail on bottom half. Could use full handrail. Top 40' a priority.	min 40'
3	Cedar Path	No handrails; needs full handrail	tbd
4	Columbia Path (Lower)	No handrails; needs full handrail. Note: BPWA ordered handrails Jun 2020. To be installed summer 2020.	247'
5	Covert Path (Lower)	Handrail at top, could use full coverage	tbd
6	Glendale Path (Middle)	Handrail at top/ middle. Could use full handrail. Bottom 25' a priority.	min 25'
7	Halkin Walk (Upper)	Partial; some handrail on lower third. More needed in mid-section.	tbd
8	John Muir Path	No handrails; handrail needed on bottom part with stairs	tbd
9	Miller Path East	Handrail at top, needs full coverage.	tbd
10	Northgate Path	Handrail in mid-section. Needs coverage on bottom and top sections.	tbd
11	Poppy Path	No handrails; could use full handrail.	335'
12	Shasta Path	No handrails; needs full handrail.	tbd
13	Stevenson Path (Lower)	No handrails; needs full coverage.	267'
14	Stoddard Path	None; could use full handrail except for flat part by Grizzly Peak Blvd.	tbd
15	Tilden Path	None; entire length is steep	tbd
16	Wildcat Path* *located in Park Hills	None; not a high priority for handrails as path is not heavily used	tbd
17	Wilson Walk	None; entire 175' is very steep and needs handrail coverage	175'

Table 5. Major Vegetation Encroachment Issues (as documented in July 2018 BPWA survey, updated June 2020)

Note: BPWA is prioritizing these paths for our regular maintenance parties (12-15 paths/ year)

	Path	Vegetation issues documented in July 2018 survey	Updates since July 2018 survey (if any)
1	Acacia Walk	needs weeding, some debris & overgrown grass, ivy	
2	Alta Vista Path	needs weeding, ivy in path, vegetation obstructs upper sign	BPWA maintenance party planned Jul 2020
3	Betty Olds Path	seriously overgrown vegetation at top & grasses on steps; lower needs sweeping	BPWA maintenance party Oct 2018
4	Billie Jean Walk	very overgrown ivy in middle section encroaching and partially covering railing; veg obstructing upper sign	BPWA maintenance party Mar 2019
5	Bret Harte Path	needs weeding (seriously!) at top half; top sign is partially obstructed	BPWA maintenance party Sep 2019; BPWA contractor weed-whacked Jun 2020
6	Cedar Path	middle of path needs weeding on steps; overhead ivy needs clipping; lower sign obstructed by vegetation	BPWA contractor weed-whacked Jun 2019 and Jun 2020; BPWA maintenance party Feb 2020
7	Garber Path	needs vegetation cleaned	
8	Halkin Walk (Upper)	needs weeding	
9	Miller Path East	heavy weeds b/w steps and on flat sections	BPWA contractor weed-whacked Jun 2019 and Jun 2020
10	Orchard Lane (Upper)	vegetation obstructs railing	BPWA maintenance party Dec 2018
11	Pine Path	vegetation obstructs handrail, overhanging tree, needs sweeping	
12	Redwood Terrace	new growth at base of redwood tree should be cut back	Parks Dept cleared path Aug 2019; BPWA small work party Jun 2020
13	Shasta Path	needs weeding; low branches; sign at the top is fully obstructed by vegetation	BPWA maintenance party Sep 2018
14	Stevenson Path (Lower)	ivy, weeds, low branches; roots in path (tripping hazard); lower sign obstructed by vegetation	
15	Stevenson Path (Upper)	very overgrown; needs work party.	BPWA maintenance parties Jan and Jun 2019; BPWA contractor weed-whacked Jun 2020 (top/bottom outside gates)
16	Tanglewood Path	needs weeding, sweeping, tree trimming, handrail partially obstructed	Work by unk. party (neighbor?) Feb 2020
17	Whitaker Path	lower path needs trimming back & sweeping	BPWA maintenance party Aug 2018
18	Wildcat Path* *path located in Park Hills	low branches, needs weeding and sweeping, path is very narrow at times	BPWA to contact Park Hills about weeding this path
19	Wilson Walk	needs sweeping, weeding, big plant encroaching mid way	BPWA fixed broken steps Oct 2018; BPWA contractor weed-whacked Jun 2019 and Jun 2020

Attachment A

List of Paths Improved by BPWA (as of June 2020)

1997-2002:

1. Oak Street Path
2. Keeler Path
3. Latham Walk
4. Anne Brower Path
5. Mosswood Lane
6. Acacia Walk
7. Atlas Path

2003:

8. Sterling Path
9. Stoddard Path

2004:

10. Upper Stevenson Path
11. Lower Stevenson Path
12. Wilson Walk
13. Upper Glendale Path

2005:

14. Columbia Walk
15. Lower Glendale Path
16. Acacia Steps
17. Upper Covert Path

2006:

18. Bret Harte Path
19. Middle Glendale Path
20. Cedar Street Path
21. Poppy Path

2007:

22. Shasta Path
23. Whitaker Path

2008:

24. Upper El Mirador Path
25. Ina Coolbrith (was Bret Harte Lane)

2009:

26. Lower Covert Path

2010:

27. Northgate Path

2011:

28. Miller Path East
29. Wildcat Path (path #80)

2012:

30. LaLoma Path

2013:

31. Betty Olds Path (was #68 Twain)

2014:

32. Upper Halkin Walk

2015:

33. Tilden Path

2016:

34. John Muir Path (was Keeler Walk)

2020:

35. Lower Columbia Path
36. Lower Halkin Walk (in progress)

Attachment B
List of Unbuilt Paths (as of June 2020)

Count	Path Name	Path No	Lower Address	Upper Address	Notes
1	Avenida Path	93	130-140 Avenida Dr.	1448-1452 Grizzly Peak Blvd.	completely blocked top & bottom
2	Columbia Path (Upper)	88	1399-1407 Queens Rd.	17-18 Columbia Circle	surveyed, large eucalyptus in ROW, steep rock at bottom; emailed PW and Parks - hoping City removes tree so BPWA can develop the path.
3	Cragmont Path	58	1177-1197 Cragmont Ave.	1166-1170 Keeler Ave.	completely encroached at top: 1166 Keeler
4	Delmar Path	86	opposite 1421 Glendale Ave.	31-35 Delmar Ave.	more or less unencroached, very steep
5	Devon Lane (Upper)	8	763-765 San Diego Rd.	163-168 Southampton Ave.	surveyed, severe encroachment at top 168 Southampton
6	Eleanor Path	59	dead end	1160-1168 Keith Ave.	
7	Grizzly Path	91	185 Hill Rd. & 1371 Grizzly Peak Bl.	1328-1336 Summit Rd.	more or less unencroached, very steep; neighbors aware of path and would like it built.
8	Halkin Walk (Lower)	30	695-701 Cragmont Ave.	698-700 Euclid Ave.	in progress; to be completed in 2020
9	Harding Path	94	west of 1569 Campus Dr.	1504-1510 Olympus Ave.	large eucalyptus in ROW at bottom of path; emailed PW and Parks - hoping City removes tree so BPWA can develop the path.
10	Highland Path	111	Highland Ave. & Ridge Rd.	dead end at Lawrence Berkeley Lab	
11	Hilgard Path	108	1647-1675 La Loma Ave.	south of 1616 La Vereda Rd.	wide ROW, retaining wall bottom: 1645 LaLoma; neighbors aware of path and would like it built
12	Hill Path	66	1251-1269 Grizzly Peak Blvd.	80-100 Hill Rd.	more or less unencroached, very steep
13	Laurel Lane	10	767-771 San Diego Rd.	dead end to private property	
14	Le Conte Path	110	top of Le Conte Ave.	dead end at Lawrence Berkeley Lab	
15	Middle Bret Harte Path	71	1099-1105 Sterling Ave.	1096-1100 Miller Ave.	completely encroached at top: 1096 Miller
16	Miller Path West	42	1011-1013 Miller Ave.	998-1002 Grizzly Peak Blvd.	completely blocked: fences across top, middle, bottom
17	Parnassus Path	87	3079-3085 Buena Vista Way	8-9 West Parnassus Ct.	bottom end not clear who owns: 3079 & 3085 Buena Vista
18	Path 74	74	Wildcat Canyon Rd.	Hillview Rd. & Woodside Rd.	in Park Hills neighborhood
19	Shasta Walk	63	1187-1195 Keeler Ave.	2885-2887 Shasta Rd.	hot tub in ROW at bottom 1187 Keeler
20	Summit Path	92	1419-1425 Grizzly Peak Blvd.	1396-1400 Summit Rd.	large redwood in path ROW was removed years ago, but suckers are blocking the way now; neighbors aware of path and would like it built.
21	Twain Way	55	1137-1149 Cragmont Ave.	1122-1124 Keeler Ave.	
22	Wilson Path	95	1585-1589 Campus Dr.	1572-1580 Olympus Ave.	need survey at top, retaining walls bottom: 1589 Campus Dr.

Attachment C - Handrail Inventory on Existing Paths (as of June 2020)

	Path	Handrail Coverage	Handrail Location	More needed, at least on steep sections
1	Alta Vista Path	Full	Side	
2	Arden Steps	Full	Side	
3	Bancroft Steps	Full	Center	
4	Billie Jean Walk	Full	Alternates	
5	Covert Path (Upper)	Full	Side	
6	El Mirador Path (Lower)	Full	Side	
7	Eunice Steps	Full	Center	
8	Fountain Walk	Full	Center	
9	Glendale Path (Lower)	Full	Side	
10	Ina Coolbrith Path	Full	Side	
11	La Loma Path	Full	Side	
12	Le Roy Steps	Full	Center	
13	Martinez Path	Full	Center	
14	Maryland Walk	Full	Side	
15	North Path	Full	Side	
16	Oakridge Steps	Full	Center	
17	Rose Steps	Full	Side	
18	The Steps	Full	Center	
19	Whitaker Path	Full	Side	
20	Acacia Walk	Partial	Side	
21	Arden Path	Partial	Side	✓
22	Avalon Walk	Partial	Side	
23	Berryman Path - Middle	Partial	Side	
24	Berryman Path - Upper	Partial	Side	
25	Bret Harte Path	Partial	Alternates	✓
26	Bret Harte Way	Partial	Side	
27	Claremont Path	Partial	Side	
28	Columbia Walk	Partial	Side	
29	Covert Path (Lower)	Partial	Side	✓
30	Easter Way Lower	Partial	Center	✓
31	Easter Way Middle	Partial	Alternates	
32	El Mirador Path (Upper)	Partial	Side	
33	El Paseo (Lower)	Partial	Side	✓
34	El Paseo (Upper)	Partial	Side	
35	Florida Walk	Partial	Center	
36	Fred Herbert Path (Upper)	Partial	Side	✓
37	Garber Path	Partial	Side	✓
38	Glendale Path (Middle)	Partial	Side	✓
39	Glendale Path (Upper)	Partial	Side	
40	Halkin Walk (Upper)	Partial	Side	✓
41	Hawthorne Steps	Partial	Center	
42	Hill Court Steps	Partial	Side	
43	Indian Rock Path (Arlington Ave to Indian Rock Ave)	Partial	Center	
44	Indian Rock Path (Contra Costa Ave to Mendocino Ave)	Partial	Side	

	Path	Handrail Coverage	Handrail Location	More needed, at least on steep sections
45	La Loma Steps	Partial	Side	
46	La Vereda Steps	Partial	Side	
47	Miller Path East	Partial	Not recorded	✓
48	Mosswood Lane	Partial	Not recorded	
49	Northgate Path	Partial	Side	✓
50	Oak Street Path - East Segment	Partial	Side	
51	Orchard Lane (Upper)	Partial	Alternates	✓
52	Oxford School Way	Partial	Side	
53	Park Path	Partial	Center	✓
54	Patty Kates Path	Partial	Side	
55	Pine Path	Partial	Side	
56	Pinnacle Path	Partial	Side	
57	Poplar Path	Partial	Side	
58	Redwood Terrace	Partial	Side	
59	Rock Walk	Partial	Side	
60	Santa Barbara Path	Partial	Side	
61	South Crossways	Partial	Side	
62	Sterling Path	Partial	Alternates	
63	Tamalpais Path	Partial	Side	
64	Tanglewood Path	Partial	Side	
65	Terrace Walk - Lower	Partial	Side	
66	The Cutoff	Partial	Center	
67	The Footway	Partial	Center	
68	Tunbridge Lane	Partial	Side	✓
69	Upton Lane	Partial	Side	
70	Vine Lane	Partial	Side	
71	Willow Walk	Partial	Side	
72	Yosemite Steps Lower	Partial	Side	
73	Yosemite Steps Upper	Partial	Side	✓
74	Acacia Steps	None		✓
75	Anne Brower Path	None		
76	Atlas Path	None		✓
77	Berryman Path - Lower	None		
78	Betty Olds Path (was Mark Twain)	None		
79	Black Path	None		
80	Boynton Walk	None		✓
81	Cedar Path	None		✓
82	Chester Lane	None		
83	Columbia Path (Lower)	None		✓
84	Crescent Park Path	None		
85	Devon Lane (Lower)	None		✓
86	Easter Way Upper	None		
87	Encina Walk	None		
88	Fred Herbert Path (Lower)	None		
89	Fred Herbert Path (Middle)	None		

	Path	Handrail Coverage	Handrail Location	More needed, at least on steep sections
90	Geneva's Path	None		
91	Glen Rose Alley	None		✓
92	Great Stoneface Path	None		
93	Holmes Path	None		✓
94	Indian Rock Path (Mendocino Ave to Arlington Ave)	None		
95	Indian Rock Path (The Alameda to Contra Costa Ave)	None		
96	Indian Trail	None		
97	John Muir Path (was Keeler Walk)	None		✓
98	Keeler Path	None		
99	Keoncrest Path	None		
100	Latham Walk	None		
101	Mendocino Path	None		
102	Oak Knoll Path	None		✓
103	Oak Street Path - West Segment	None		✓
104	Oakridge Path East	None		✓
105	Oakridge Path West	None		✓
106	Orchard Lane (Lower)	None		✓
107	Poppy Path	None		✓
108	Rose Walk	None		
109	Scott Newhall Path	None		
110	Shasta Path	None		✓
111	Stevenson Path (Lower)	None		✓
112	Stevenson Path (Upper)	None		
113	Stoddard Path	None		✓
114	Sunset Trail	None		
115	Terrace Walk - Upper	None		
116	The Crossways	None		
117	Tilden Path	None		✓
118	Vincente Walk	None		
119	Visalia Steps	None		✓
120	Vistamont Trail	None		
121	Wildcat Path	None		✓
122	Wilson Walk	None		✓